Test Report No. F690101/LF-CTSAYHA24-10524

MOORIM P&P CO., LTD.
3-36 Ubonggangyang-ro, Onsan-eup
Ulju-gun, Ulsan
Korea

The following sample(s) was/were submitted and identified by/on behalf of the client as:-

SGS File No.	:	AYHA24-10524
Sample Description	:	Woodfree printing paper
Style no./Item no.	:	-
Order No.	:	-
Buyer	:	-
Manufacturer	:	-
Country of Origin	:	-
Country of Destination	:	-
Received Date	:	2024. 07. 26
Test Period	:	2024. 07. 26 to 2024. 08. 02
Test Method	:	For further details, please refer to following page (s)
Test Results	:	For further details, please refer to following page (s)
Report Comments	:	The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report is not related to Korea Laboratory Accreditation Scheme.
Result Summary	:	

Test Requested	Conclusion
ISO 8124-3:2020/Amd.1:2023– Migration of Certain Elements	**See result**

Monet Jeong

Monet Jeong

Technical Manager / SGS Korea Co., Ltd

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at https://www.sgs.com/en/terms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s).

SGS Korea Co., Ltd. 322, The O valley, 76, LS-ro, Dongan-gu, Anyang-si, Gyeonggi-do, Korea 14117
t +82 (0)31 4608 000 f +82 (0)31 4608 059 http://www.sgsgroup.kr

Member of the SGS Group (Société Générale de Surveillance)

Results :

ISO 8124-3:2020/Amd.1:2023- Migration of certain elements

Test method : With reference to ISO 8124-3:2020/Amd.1:2023. Analysis was performed by ICP-OES.

Test Item(s)	Sb	As	Ba	Cd	Cr	Pb	Hg	Se	B
Migration Limit (mg/kg) - Any toy material given in Clause 1, except modelling clay and putty, finger paint, and slime	60	25	1 000	75	60	90	60	500	-
MDL (mg/kg)	5	2.5	10	5	2.5	5	2.5	10	10
Sample No.	Adjusted Migration Result(s) (mg/kg)								
1.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.	N.D.

Sample Description :

1. White paper

Note: (1) N.D. = Not detected (< MDL)
(2) MDL = Method Detection Limit
(3) Results shown are of the adjusted analytical result.

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at https://www.sgs.com/en/terms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s).

SGS Korea Co., Ltd. 322, The O valley, 76, LS-ro, Dongan-gu, Anyang-si, Gyeonggi-do, Korea 14117
t +82 (0)31 4608 000 f +82 (0)31 4608 059 http://www.sgsgroup.kr

Member of the SGS Group (Société Générale de Surveillance)

Picture of Sample as Received :



AYHA24-10524

*** End of Report ***

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at https://www.sgs.com/en/terms-and-conditions/terms-e-document. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s).

SGS Korea Co., Ltd. 322, The O valley, 76, LS-ro, Dongan-gu, Anyang-si, Gyeonggi-do, Korea 14117
t +82 (0)31 4608 000 f +82 (0)31 4608 059 http://www.sgsgroup.kr

Member of the SGS Group (Société Générale de Surveillance)